

CONFIDENTIAL

Cold news!

12 February 1959file: Firing Device, A.C.
Delay MK II

Dear Joe,

Enclosed is the information on the Mark II AC Delay
that you requested on the phone yesterday.

Total number of units opened and inspected -- 662
(Including 57 cans not previously opened)

From the above cans, the following numbers of
ampoules were found to have or were still leaking:

132 gold
24 red
16 black
9 silver
17 blue
11 green
14 yellow
12 brown (violet)
235 or 4.4% of the total ampoules

In addition, three of the firing devices still sealed
in scrim bags had fired and had punctured three green capsules
directly in front of the devices. Unfortunately, it was not
possible at the time we performed this operation to observe
exactly which ampoule had been responsible for the firing
of the device, and possibly when you come out in a couple of
weeks, we can go over some more cans and see whether any of
them have fired in a similar manner and determine at that
time which ampoule is responsible.

Enclosed is an AC Delay body as we found it in the can
and also a 1 oz. sample of the E-910 adhesive from Eastman
that you requested.

Regards

to on the phone work links .
CONFIDENTIAL